



GEJ4656 Installation Instructions


Molded-Case Circuit Breakers

Mounting Lugs for K1200 Circuit Breakers

Installation Instructions for
TCAL41, TCAL61, TCAL81, TCAL91, TCAL121, TCAL124, TCAL125,
TCAL 131, TCAL134, TC4212, TC4213A, TCO41, TCO61, TCO81A,
TCO91, TCO121, TCO131, TCO125

For satisfactory performance, lugs must be securely fastened to terminal strips. Lugs are mounted at the factory with a high-torque wrench, set at 200 inch-pounds minimum.

Suggested method for attachment or removal is illustrated.



These instructions do not cover all details or variations in equipment nor do they provide for every possible contingency to be met in connection with installation, operation or maintenance. Should further information be desired or should particular problems arise that are not covered sufficiently for the purchaser's purposes, the matter should be referred to the General Electric Company. These instructions are intended for use by qualified personnel only.

GE Electrical Distribution & Control

General Electric Company
41 Woodford Ave., Plainville, CT 06062
© 1994 General Electric Company

GEJ4656 0294 PSA
Rev. 5