



GE Zenith Controls

Dear customer,

In order to obtain the latest version of GEZC's MX50 Factory Configuration Software (50P-1171 Rev1.5), please follow the steps below.

- Step 1:** Move mouse to the bottom left of desktop, right click on 'Start'. Then left click on 'Explore' to open a Window Explorer (not Internet Explorer).
- Step 2:** Left click on the local drive "C:\TEMP". Then create a sub folder called "50P-1171" within "C:\TEMP". The path to the subfolder will become "C:\TEMP\50P-1171"
- Step 3:** Before entering the link into an Internet Browser, please read the following:
a) All characters in the link (shown in Step 3d) are **case sensitive!**
b) Be sure to enter the 2 (two) symbols correctly. These are vertical bars '|' and neither forward nor back slashes
<http://www.geindustrial.com/publibrary/checkout/Software|50P-1171|generic>
c) The file size of the zip file is 11.6MB, downloading time will greatly depend on the Internet speed.
d) Open an Internet Explorer (not Window Explorer) and enter the link below to download the zip file of interest (50P-1171 Rev1_5.zip) into the subfolder "C:\TEMP\50P-1171" created in Step 2.
<http://www.geindustrial.com/publibrary/checkout/Software|50P-1171|generic>
- Step 4:** Extract all the files from the zip into the same subfolder (e.g. C:\temp\50P-1171) as created in Step 2.
- Step 5:** In "C:\temp\50P-1171", double click the file "setup.exe" and follow the onscreen instructions to complete the software installation.
- Step 6:** To open the software, click –
Start > Programs > MX50 Configuration Software Rev1_5.exe
The opening page of the software is displayed as below.

